

DEC 11 2014

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

Operator Name CHEVRON	API Number 3002538641
Property Name Central Vacuum Unit	Well No. 459

Surface Location

U/L - Lot 0	Section 31	Township 17S	Range 35E	Feet from 1050	N/S Line N	Feet From 566	E/W Line W	County Lca
----------------	---------------	-----------------	--------------	-------------------	---------------	------------------	---------------	---------------

Well Status

Well Status	SHUT-IN	PRODUCING	DATE 11-19-14
-------------	---------	-----------	------------------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A) Surf-Interm	(B) Interm(1)-Interm(2)	(C) Interm-Prod	(D) Prod Casing	(E) Tubing
Pressure	0			290	1850
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	
Steady Flow	Y / N	Y / N	Y / N	Y / N	
Surges	Y / N	Y / N	Y / N	Y / N	
Down to nothing	Y / N	Y / N	Y / N	Y / N	
Gas or Oil	Y / N	Y / N	Y / N	Y / N	
Water	Y / N	Y / N	Y / N	Y / N	

If bradenhead flowed water, check all of the descriptions that apply:


CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks: INJECTING AT THIS TIME ___ WTR, ___ GAS, ☒ CO2

Oil on production Casing blew down to 0 psi
Returned 24 hrs later - production casing had
Risen back to 100 psi

FOR RECORD ONLY

Faded Letter 8/2014 BS 12/12/2014

Signature:  DQKB	OIL CONSERVATION DIVISION
Printed name: Daniel Pace	Entered into RBDMS
Title: FSA	Re-test
E-mail Address: DQKB@chevron.com	
Date: 11-14	Phone: (575) 704 - 2365
Witness:	

DEC 15 2014