

DEC 11 2014

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

Operator Name CHEVRON					API Number 3002538786 ✓				
Property Name Vacuum Grayburg San Andres Unit					Well No. 439 ✓				
1. Surface Location ✓									
UL - Lat B	Section 01	Township 18S	Range 34E	Feet from 634	N/S Line N	Feet From 1632	E/W Line E	County Lea	

Well Status

Well Status	SHUT-IN	PRODUCING	DATE 11-19-14
-------------	---------	-----------	------------------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A)Surf-Interm	(B)Interm(1)-Interm(2)	(C)Interm-Prod	(D)Prod Casing	(E)Tubing
Pressure	0			300	1300
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	
Steady Flow	Y / N	Y / N	Y / N	0 / N	
Surges	Y / N	Y / N	Y / N	Y / N	
Down to nothing	Y / N	Y / N	Y / N	0 / N	
Gas or Oil	Y / N	Y / N	Y / N	Y / N	
Water	Y / N	Y / N	Y / N	Y / N	

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------


Remarks:

INJECTING AT THIS TIME ___ WTR. ___ GAS. X CO2

Production Casing took 30 min to blow down to 0 psi
Returned 24 hrs later it had risen back to 100 psi

FOR RECORD ONLY

Failed better
3/25/14
BS
12/12/2014

Signature: 	OIL CONSERVATION DIVISION
Printed name: Daniel Pace	Entered into RBDMS
Title: FSA	Re-test
E-mail Address: DQKB@chevron.com	
Date: 11-19-14	Phone: (575) 704 - 2365
Witness:	

DEC 15 2014