

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

DEC 10 2014

BRADENHEAD TEST REPORT

RECEIVED

Operator Name ConocoPhillips		API Number 3002500610
Property Name MCA		Well No. 67

Surface Location

LL - Lot L	Section 21	Township 17S	Range 32E	Feet from 1980	N/S Line FSL	Feet From 660	E/W Line FWL	County Lea
----------------------	----------------------	------------------------	---------------------	--------------------------	------------------------	-------------------------	------------------------	----------------------

Well Status

TA'D WELL YES ☐ NO ☒	SHUT-IN YES ☐ NO ☒	INJECTOR ☒ INJ ☐ SWD	PRODUCER OIL ☒ GAS ☐	DATE 12/11/14
--	--	--	--	-------------------------

OBSERVED DATA

	(A) Surface	(B) Intermit 1	(C) Intermit 2	(D) Prod Using	(E) Tubing
Pressure		N/A	N/A	0 PSI	0 PSI
Flow Characteristics					
Flow	☒ N	Y/N	Y/N	☒ N	CO2 ☐
Steady Flow	☒ Y	Y/N	Y/N	☒ Y	WTR ☒
Surges	☒ Y	Y/N	Y/N	☒ Y	GAS ☐
Down to nothing	☒ Y	Y/N	Y/N	☒ Y	Type of Fault
Gas or Oil	☒ Y	Y/N	Y/N	☒ Y	Indicated for
Water	☒ Y	Y/N	Y/N	☒ Y	Water/Gas F applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

This well has just been repaired due to a
Packer Leak

FOR RECORD ONLY

BS 12/12/2014

Signature: Chris Silva	OIL CONSERVATION DIVISION
Printed name: CHRIS SILVA	Entered into RBDMS
Title: MSD	Re-test
E-mail Address: Christina.Silva@conocophillips.com	
Date: 12-11-14	Phone: 505-704-2252
Witness:	

DEC 17 2014