

HOBBS OCD

NOV 19 2014

RECEIVED

State of New Mexico  
Energy, Minerals and Natural Resources Department  
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

|                                      |                          |
|--------------------------------------|--------------------------|
| Operator Name<br>CHEVRON             | API Number<br>3002525798 |
| Property Name<br>Central Vacuum Unit | Well No.<br>113          |

7. Surface Location

|               |              |                 |               |                   |               |                   |               |               |
|---------------|--------------|-----------------|---------------|-------------------|---------------|-------------------|---------------|---------------|
| UL - Lot<br>L | Section<br>6 | Township<br>18S | Range<br>35 E | Feet from<br>1620 | N/S Line<br>S | Feet From<br>1100 | E/W Line<br>W | County<br>Lea |
|---------------|--------------|-----------------|---------------|-------------------|---------------|-------------------|---------------|---------------|

Well Status

|                        |                  |                     |
|------------------------|------------------|---------------------|
| Well Status<br>SHUT-IN | PRODUCING<br>INJ | DATE<br>11 NOV 2014 |
|------------------------|------------------|---------------------|

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

|                      | (A)Surf-Interm | (B)Interm(1)-Interm(2) | (C)Interm-Prod | (D)Prod-Csing | (E)Tubing |
|----------------------|----------------|------------------------|----------------|---------------|-----------|
| Pressure             |                |                        |                |               |           |
| Flow Characteristics |                |                        |                |               |           |
| Puff                 | Y / N          | Y / N                  | Y / N          | Y / N         |           |
| Steady Flow          | Y / N          | Y / N                  | Y / N          | Y / N         |           |
| Surges               | Y / N          | Y / N                  | Y / N          | Y / N         |           |
| Down to nothing      | Y / N          | Y / N                  | Y / N          | Y / N         |           |
| Gas or Oil           | Y / N          | Y / N                  | Y / N          | Y / N         |           |
| Water                | Y / N          | Y / N                  | Y / N          | Y / N         |           |

If bradenhead flowed water, check all of the descriptions that apply:

|       |       |       |        |       |
|-------|-------|-------|--------|-------|
| CLEAR | FRESH | SALTY | SULFUR | BLACK |
|-------|-------|-------|--------|-------|

Remarks:


INJECTING AT THIS TIME \_\_\_ WTR. \_\_\_ GAS, \_\_\_ CO2

Big Currently on well

no test

FOR RECORD ONLY

BS 12/10/2014

|                                                                                                |                           |
|------------------------------------------------------------------------------------------------|---------------------------|
| Signature:  | OIL CONSERVATION DIVISION |
| Printed name: Daniel Pace                                                                      | Entered into RBDMS        |
| Title: FSA                                                                                     | Re-test                   |
| E-mail Address: DQKB@chevron.com                                                               |                           |
| Date: 11-9-14                                                                                  | Phone: (575) 704 - 2365   |
| Witness:                                                                                       |                           |

DEC 17 2014