

HOBBSOCD

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

DEC 26 2014

BRADENHEAD TEST REPORT

RECEIVED

Operator Name <i>midland Operating</i>		API Number <i>30-025-23112</i>
Property Name <i>Largie Martin Woodworth</i>		Well No. <i>204</i>

Surface Location

U/Lot <i>14</i>	Section <i>28</i>	Township <i>24S</i>	Range <i>37E</i>	Feet from <i>330</i>	N/S Line <i>S</i>	Feet From <i>330</i>	E/W Line <i>W</i>	County <i>LRA</i>
--------------------	----------------------	------------------------	---------------------	-------------------------	----------------------	-------------------------	----------------------	----------------------

Well Status

TA'D WELL ☒ YES	NO	SHUT-IN ☒ YES	NO	INJECTOR ☒ INJ	SWD	PRODUCER OIL	GAS	DATE <i>11/3/2014</i>
--	----	--	----	---	-----	-----------------	-----	--------------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Casing	(E)Tubing
Pressure	ϕ			ϕ	ϕ
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	CO2 ___
Steady Flow	Y / N	Y / N	Y / N	Y / N	WTR ___
Surges	Y / N	Y / N	Y / N	Y / N	GAS ___
Down to nothing	Y / N	Y / N	Y / N	Y / N	Type of Fluid
Gas or Oil	Y / N	Y / N	Y / N	Y / N	Injected for
Water	Y / N	Y / N	Y / N	Y / N	Waterflood if applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

SASOCD
FOR RECORD ONLY

Signature:		OIL CONSERVATION DIVISION
Printed name:		Entered into RBDMS
Title:		Re-test
E-mail Address:		
Date: <i>11/3/2014</i>	Phone:	
Witness: <i>[Signature]</i>		

JAN 07 2015