

DEC 26 2014

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

Operator Name <i>midland OPERATING</i>	API Number <i>30-25-25310</i>
---	----------------------------------

Property Name <i>Langle Matrix Woolworth</i>	Well No. <i>710</i>
---	------------------------

Surface Location									
UL - Lot <i>11</i>	Section <i>27</i>	Township <i>24S</i>	Range <i>37E</i>	Feet from <i>1950</i>	N/S Line <i>N-</i>	Feet from <i>50</i>	E/W Line <i>E</i>	County <i>Lea</i>	

Well Status									
TA'D WELL ☒ YES	NO	SHUT-IN ☒ YES	NO	INJECTOR ☒ IN	SWD	OIL PRODUCER	GAS	DATE <i>12/31/2014</i>	

OBSERVED DATA

	(A)Surface	(B)Interm-1	(C)Interm-2	(D)Prod-Casing	(E)Tubing
Pressure	ϕ	N/A	N/A	ϕ	0
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	CO2 —
Steady Flow	Y / N	Y / N	Y / N	Y / N	WTR —
Surges	Y / N	Y / N	Y / N	Y / N	GAS —
Down-to-nothing	Y / N	Y / N	Y / N	Y / N	Type of Fluid
Gas or Oil	Y / N	Y / N	Y / N	Y / N	Injected for
Water	Y / N	Y / N	Y / N	Y / N	Waterflood if
					applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

FOR RECORD ONLY

JAS/OCD

Signature:	OIL CONSERVATION DIVISION
Printed name:	Entered into RBDMS
Title:	Re-test
E-mail Address:	
Date: <i>10/31/2014</i>	Phone:
Witness: <i>[Signature]</i>	

JAN 07 2015

fr