French Dr., Hobbs, NM 88240
(575) 393-6161 Fax (575) 393-0720

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name	API Number
Kevin O. Butler	30-005-01161
Property Name	**Well No.**
South Caprock Queen	15

Surface Location

UL - Lot	Section	Township	Range		Feet from	N/S Line	Feet From	E/W Line	County
O	28	14S	31E		330	S	1980	E	Chaves

Well Status

TA'D WELL		SHUT-IN		INJECTOR		PRODUCER		DATE
YES	NO	YES	NO	INJ	SWD	OIL	GAS	12/29/14

OBSERVED DATA

	(A) Surface	(B) Interm-1	(C) Interm-2	(D) Prod Csng	(E) Tubing
Pressure	0	N/A	N/A	0	0
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	CO2 ___
Steady Flow	Y / N	Y / N	Y / N	Y / N	WTR X
Surges	Y / N	Y / N	Y / N	Y / N	GAS ___
Down to nothing	Y / N	Y / N	Y / N	Y / N	Type of Fluid Injected for Waterflood if applies
Gas or Oil	Y / N	Y / N	Y / N	Y / N	
Water	Y / N	Y / N	Y / N	Y / N	

Remarks – Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

BS 1/29/2015

Signature:	OIL CONSERVATION DIVISION
Printed name:	Entered into RBDMS
Title:	Re-test
E-mail Address:	
Date: 12/29/14 Phone:	
Witness:	

JAN 20 2015