Submit One Copy To Appropriate District	State of New Mexico		30-025-0739 Form C-103
Office District I	Energy, Minerals and Natural Resources		Revised November 5, 2013
1625 N. French Dr., Hobbs, NM 88240		WELL API NO:: 30-015-32559	
District II 811 S. First St., Artesia, NM 88210 OIL CONSERVATION DIVISION		DIVISION	5. Indicate Type of Lease
District III 1220 South St. Francis Dr.		STATE FEE 🗵	
1000 Rio Brazos Rd., Aztec, NM 87410 District IV Santa Fe, NM 87505		6. State Oil & Gas Lease No.	
1220 S. St. Francis Dr., Santa Fe, NM 87505	· ·		
SUNDRY NOTICES AND REPORTS ON WELLS			7. Lease Name or Unit Agreement Name:
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH			Fred Turner
PROPOSALS.)			8. Well Number: 002
1. Type of Well: Oil Well Gas Well Other: Injection			
2. Name of Operator: Chevron, USA INC			9. OGRID Number: 4323
3. Address of Operator: 15 Smith Road, Midland, TX 79705			10. Pool name or Wildcat: SWD;SAN
			ANDRES (Oil & Gas)
	06 Township: 20S Range: 38E; 66	50 feet from the So	uth line and 1980 feet from the East line
NMPM County Lea		· · · · · · · · · · · · · · · · · · ·	
	11. Elevation (Show whether DR,	, RKB, RT, GR, etc.	.): 3568
12. Check Appropriate Box to	Indicate Nature of Notice, R	eport or Other I	Data
NOTICE OF IN	TENTION TO	l cum	DEFOUENT DEPORT OF
NOTICE OF IN PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON 🛛	REMEDIAL WOR	SSEQUENT REPORT OF:  RK
TEMPORARILY ABANDON	CHANGE PLANS	1	RILLING OPNS. P AND A
PULL OR ALTER CASING	MULTIPLE COMPL	CASING/CEMEN	
OTHER:	MOETH 22 00M 6		ready for OCD inspection after P&A
	compliance with OCD rules and the		erator's pit permit and closure plan.
Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned.			
A steel marker at least 4" in diar	neter and at least 4' above ground	level has been set i	n concrete. It shows the
			UARTER/QUARTER LOCATION OR
	N, TOWNSHIP, AND RANGE. PED ON THE MARKER'S SUR		ON HAS BEEN WELDED OR
CERMANENTET STAME	EDON THE WARREN S SUR	FACE.	
	nearly as possible to original grou	nd contour and has	been cleared of all junk, trash, flow lines and
other production equipment.			
Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level.			
☐ If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with			
OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed			
from lease and well location.  All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have			
to be removed.)	is have been removed. I bruible bu	ises have been rem	Oved. (I dured onsite conciete bases do not have
· ·	is have been addressed as per OCD	rules.	
			C. All fluids have been removed from non-
retrieved flow lines and pipelines.			
		ical service poles ar	nd lines have been removed from lease and well
location, except for utility's distributi	on infrastructure,		3m.
When all work has been completed, r	eaturn this form to the annionriate l	District office to se	hedule an inspection
which are work has been completed, i	ctum uns tom to the appropriate i	District office to se	nçuuic un inspection.
O. 211			/ /
SIGNATURE:	TITLE: _	Construction Rep	DATE: 12/16/14
TYPE OR PRINT NAME: Jon Ry	iff D.MAH - imier	Ochevron com	PHONE: 016-708-8248
For State Use Only			
M , /	W. 1 1	$\int_{\mathbb{R}^{n}}$	
APPROVED BY:	Whatakam TITLE:	Longstian	u Officer DATE: 1/29/2015
Conditions of Approval (if any):			

M