

State of New Mexico
 Energy, Minerals and Natural Resources Department
 Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name

E L

Property Name

30-02

23

12

1

Surface Location

U/L

Lot

Section

Township

Range

Feet from

N/S Line

Feet from

E/W Line

County

2

1

13

20 S

2

N

1980

W

Lea

37E

Well Status

YES

TAPO WELL

YES

SHUT-D

IN

INJECTOR

SWD

OIL

PRODUCER

GAS

2, 15

AT

OBSERVED DATA

	LAISURANCE	LAISURANCE	LAISURANCE	LAISURANCE
Pressure			N	
Flow Characteristics				
Flow	Y/N	Y/N	Y/N	Y/N
Steady flow	Y/N	Y/N	Y/N	Y/N
Bubbles	Y/N	Y/N	Y/N	Y/N
Down to bottom	Y/N	Y/N	Y/N	Y/N
Gas or Oil	Y/N	Y/N	Y/N	Y/N
Water	Y/N	Y/N	Y/N	Y/N

Remarks - Please state out each string (A,B,C,D,E) pertinent information regarding observed down or continuous coming up it applies.

BS 2/10/2015

Signature

David Lubin

Printed name

Title

E-mail Address

Date

2/10/15

Phone

Business

[Signature]

OIL CONSERVATION DIVISION

Entered into RBDMS

Re-test

FEB 11 2015