

HOBBSOCD

FEB 19 2015

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

Operator Name MARK Khergy		API Number 30-025 36938
Property Name LIA KS		Well No. 6

Surface Location									
UL	Lot	Section	Township	Range	Feet from	NS Line	Feet from	EAV Line	County
I		35	17S	33E	2310	5	990	E	Lea

Well Status									
YES	TA'D WELL	NO	YES	SHUT-IN	NO	INJ	SWD	PRODUCER	GAS
									2/19/15

OBSERVED DATA

	(A) Surface	(B) Inflow	(C) Interim 2	(D) Prod. Case	(E) Tubing
Pressure	0	N/A	N/A	30	50
Flow Characteristics					
Pure	YES	YES	YES	YES	CO2
Steady flow	YES	YES	YES	YES	WTR
Surges	YES	YES	YES	YES	GAS
Downflow running	YES	YES	YES	YES	Type of Fluid
Gas or Oil	YES	YES	YES	YES	Upstream
Water	YES	YES	YES	YES	Throat & B

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous bleed up if applies.

PR 2/20/2015

Signature: [Signature]	OIL CONSERVATION DIVISION
Printed name:	Entered into RBDMS
Title:	Re-test
E-mail Address:	
Date: 2/19/15	Phone:
Witness: [Signature]	

FEB 23 2015

R.