

HOBBSOCD

State of New Mexico
Energy, Minerals and Natural Resources Department FEB 19 2015
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

RECEIVED

Operator Name MAK Energy		AD Number 30-025-37106
Property Name Daver State		Well No. 1

Surface Location									
U1. Lot G	Section 9	Township 18S	Range 34E	Feet from 2310	N/S Line N	Feet from 1700	E/W Line E	County Lea	



Well Status									
YES	TA'D WELL NO	YES	SHUT-IN NO	INJ	INJECTOR NO	SWD	OIL NO	PRODUCER NO	GAS NO
									DATE 2/19/15

OBSERVED DATA

	(A) Surface	(B) Interval 1	(C) Interval 2	(D) Interval 3	(E) Interval 4
Pressure	ϕ	N/A	N/A	20	20
Flow Characteristics					
Flow	Y/N	Y/N	Y/N	Y/N	Y/N
Steady flow	Y/N	Y/N	Y/N	Y/N	Y/N
Bubbles	Y/N	Y/N	Y/N	Y/N	Y/N
Downing running	Y/N	Y/N	Y/N	Y/N	Y/N
Gas or Oil	Y/N	Y/N	Y/N	Y/N	Y/N
Water	Y/N	Y/N	Y/N	Y/N	Y/N

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding closed down or continuous build up if applies.

BS 2/20/2014

Signature: 	OIL CONSERVATION DIVISION
Printed name: J. A. Brown	Entered into REDMS
Title: Inspector	Re-test
E-mail Address: jbrown@nmsd.gov	
Date: 2/19/15	Phone: 505-293-6161
Witness: 	

FEB 23 2015

h