

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

HOBBS OCD

MAR 05 2015

RECEIVED

Operator Name Linn Operating		API Number 30-025-00528	
Property Name Caprock Maljamar Unit		Well No. 13	

7. Surface Location

UL - Lot J	Section 13	Township 17S	Range 32 E	Feet from 1980	N/S Line FSL	Feet From 1980	E/W Line FEL	County Lea
----------------------	----------------------	------------------------	----------------------	--------------------------	------------------------	--------------------------	------------------------	----------------------

Well Status

TA'D WELL YES	NO	☒ YES	SHUT-IN NO	☒ INJ	INJECTOR SWD	PRODUCER OIL	GAS	DATE 2/10/15
------------------	----	---	---------------	---	-----------------	-----------------	-----	------------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	0	0	N/A	0	2256
Flow Characteristics					
Puff	Y / (N)	Y / (N)	Y / N	Y / (N)	CO2 —
Steady Flow	Y / (N)	Y / (N)	Y / N	Y / (N)	WTR ☒
Surges	Y / (N)	Y / (N)	Y / N	Y / (N)	GAS —
Down to nothing	Y / (N)	Y / (N)	Y / N	Y / (N)	Type of Fluid
Gas or Oil	Y / (N)	Y / (N)	Y / N	Y / (N)	Injected for
Water	Y / (N)	Y / (N)	Y / N	Y / (N)	Waterflood if
					applies.

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

A, B, D - Nothing

Well SI Due to Tbg at Max Allowable

BS 3/5/2015

Signature: 		OIL CONSERVATION DIVISION	
Printed name: Darren Sooter		Entered into RBDMS	
Title: Production Specialist		Re-test	
E-mail Address: dsooter@linenergy.com			
Date: 2/10/15	Phone: 575-364-9113		
Witness:			

INSTRUCTIONS ON BACK OF THIS FORM

MAR 10 2015