

MAR 05 2015

RECEIVED

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name Linn Operating		API Number 30-025-01482	
Property Name Caprock Maljamar Unit		Well No. 79	

Surface Location

UL - Lot 0	Section 19	Township 17S	Range 33E	Feet from 990	N/S Line FSL	Feet From 2310	E/W Line FEL	County Lea
----------------------	----------------------	------------------------	---------------------	-------------------------	------------------------	--------------------------	------------------------	----------------------

Well Status

TA'D WELL YES	NO	SHUT-IN YES	NO	INJECTOR INJ	SWD	PRODUCER OIL	GAS	DATE 2/10/15
------------------	----	----------------	-----------	------------------------	-----	-----------------	-----	------------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	0	N/A	N/A	0	2500
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	CO2 —
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR ✓
Surges	Y/N	Y/N	Y/N	Y/N	GAS —
Down to nothing	Y/N	Y/N	Y/N	Y/N	Type of Fluid
Gas or Oil	Y/N	Y/N	Y/N	Y/N	Injected for
Water	Y/N	Y/N	Y/N	Y/N	Waterflood if
					applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

A, & D - Both Puff

BS 3/5/2015

Signature: D Sooter	OIL CONSERVATION DIVISION
Printed name: Darren Sooter	Entered into RBDMS
Title: Production Specialist	Re-test
E-mail Address: dsooter@linnenergy.com	
Date:	Phone: 575-369-9113
Witness:	

INSTRUCTIONS ON BACK OF THIS FORM

MAR 10 2015