

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

MAR 05 2015

BRADENHEAD TEST REPORT

RECEIVED

Operator Name Linn Operating	API Number 30-025-0153a
Property Name Caprock Maljamar Unit	Well No. 99

2. Surface Location

UL - Lot N	Section 28	Township 17S	Range 33E	Feet from 660	N/S Line S	Feet From 1980	E/W Line W	County Lea
----------------------	----------------------	------------------------	---------------------	-------------------------	----------------------	--------------------------	----------------------	----------------------

Well Status

TA'D WELL YES ☒ NO	SHUT-IN YES ☒ NO	INJECTOR ☒ INJ ☐ SWD	PRODUCER OIL ☐ GAS	DATE 2/11/15
--	--	--	---	------------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	0	N/A	N/A	0	1800
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	CO2 ☐ WTR ☒ GAS ☐
Steady Flow	Y/N	Y/N	Y/N	Y/N	Type of Fluid Injected for Waterflood if applies.
Surges	Y/N	Y/N	Y/N	Y/N	
Down to nothing	Y/N	Y/N	Y/N	Y/N	
Gas or Oil	Y/N	Y/N	Y/N	Y/N	
Water	Y/N	Y/N	Y/N	Y/N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

A, D, - Nothing

BS 3/5/2015

Signature: [Signature]	OIL CONSERVATION DIVISION
Printed name: Darren Sooter	Entered into RBDMS
Title: Production Specialist	Re-test
E-mail Address: dsooter@linnenergy.com	
Date: 2/11/15	Phone: 575-364-9113
Witness:	

INSTRUCTIONS ON BACK OF THIS FORM

MAR 10 2015