

HOBBSOCD

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

MAR 03 2015

BRADENHEAD TEST REPORT

RECEIVED

Operator Name Oxy USA Inc	API Number 30-025-05686 ✓
Property Name East Eumont Unit	Well No. 60 ✓

Surface Location

UL - Lot 0	Section 22	Township 79S	Range 37E	Feet from 660	N/S Line S	Feet From 1980	E/W Line E	County Lea
----------------------	----------------------	------------------------	---------------------	-------------------------	----------------------	--------------------------	----------------------	----------------------

Well Status



TA'D WELL ☒ YES ☐ NO	SHUT-IN ☒ YES ☐ NO	INJECTOR ☒ IN ☐ SWD	PRODUCER ☐ OIL ☐ GAS	DATE 3-3-15
--	--	---	---	-----------------------

OBSERVED DATA

	(A) Surface	(B) Interm(1)	(C) Interm(2)	(D) Prod Cmg	(E) Tubing
Pressure	0 PS			0 PS	0 PS
Flow Characteristics					
Pull	☒ Y ☐ N	☐ Y ☐ N	☐ Y ☐ N	☒ Y ☐ N	CO2 ☐
Steady Flow	☐ Y ☒ N	☐ Y ☐ N	☐ Y ☐ N	☐ Y ☒ N	WTR ☒
Surges	☐ Y ☒ N	☐ Y ☐ N	☐ Y ☐ N	☐ Y ☒ N	GAS ☐
Down to nothing	☒ Y ☐ N	☐ Y ☐ N	☐ Y ☐ N	☒ Y ☐ N	Type of fluid injected for Waterflood if applies
Gas or Oil	☐ Y ☒ N	☐ Y ☐ N	☐ Y ☐ N	☐ Y ☒ N	
Water	☐ Y ☒ N	☐ Y ☐ N	☐ Y ☐ N	☐ Y ☒ N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

BS 3/4/2015

Signature: 	OIL CONSERVATION DIVISION
Printed name: Alex Estrella	Entered into RBDMS
Title: Production Tech	Re-test
E-mail Address: alex_estrella@oxy.com	
Date: 3/3/15	Phone: 575-390-9189
Witness: 	

INSTRUCTIONS ON BACK OF THIS FORM

MAR 10 2015