State of New Mexico

MAR 1 7 2015

RECEIVED

Energy, Minerals and Natural Resources Department Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

CROSS TIMBERS ENERGY, LLC										30-025-33869		
Property Name SOUTHEAST MALJAMAR GB/SA UNIT										Well No. 714		
					7. Surface Loca	tion						
		Township 17S			Feet from 1200				om)	F/W Line	County LEA	
					Well Statu	IS						
Well Status			SHUT-IN active		PRODUCING WIW				15			
If head and and					IATE TO ATMOSPI OBSERVED D		VIDUALI	LY FOR 15	MINUTE	S EACH		
If bradenhead flowed water, ch			(A)Surf-Interm		ns that apply: (B)Interm(1)-Interm(2)		(C)Interm-Prod		(D)Prod Csng		(E)Tubing	
Pressure	Pressure		215		NA		NA.		07		1800	
Flow Characteristics		<u>- </u>	247		10.77		J J TT		1 01		7800	
Puff	Puff		(Y)/ N		Y / N		Y/N		Y / 🚱			
Steady Flow			Y / (N)		Y / N		Y/N		Y / 🚷			
Surges			Y / 🔇	Y / N			Y/N			7700		
Down to nothing			Ø / N Y / 🕅	Y/N Y/N			Y/N			7/64		
Gas or Oil Water		_	Y/®	-	Y / N		Y/N Y/N		Y / Ø		_	
If bradenhead CLEAR	flowed water	FRES	of the description	ons that ap	SALTY		SULFUR		BLACK			
Remarks:						INJECT	TING AT	THIS TIMI			(AS,CO2	
	7		•		7							
orgnature:	Signature: Was Delin							OIL CONSERVATION DIVISION				
Printed name:								Entered into RBDMS				
Title:								Re-test				
E-mail Addres	SS:								- 1			
Date: 3-11-15			Phone:									
			Witness:									
									**			