

MAR 30 2015

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

Operator Name Oxy USA Inc	API Number 30-025-05530
Property Name East Eumont Unit	Well No. 9

2. Surface Location

UL - Lot 0	Section 33	Township 18S	Range 37E	Feet from 660	N/S Line S	Feet From 1650	E/W Line E	County Lea
----------------------	----------------------	------------------------	---------------------	-------------------------	----------------------	--------------------------	----------------------	----------------------

Well Status



TA'D WELL YES ☒	SHUT-IN YES ☒	INJECTOR ☒	SWD	PRODUCER OIL	GAS	DATE 3-3-15
---	---	--	-----	-----------------	-----	-----------------------

OBSERVED DATA

	(A) Surface	(B) Interm(1)	(C) Interm(2)	(D) Prod Csg	(E) Tubing
Pressure	0 psi			0 psi	1500 psi
Flow Characteristics					
Pull	☒ Y ☒ N	☒ Y ☒ N	☒ Y ☒ N	☒ Y ☒ N	CO2 ☒
Steady Flow	☒ Y ☒ N	☒ Y ☒ N	☒ Y ☒ N	☒ Y ☒ N	WTR ☒
Surges	☒ Y ☒ N	☒ Y ☒ N	☒ Y ☒ N	☒ Y ☒ N	GAS ☒
Down to nothing	☒ Y ☒ N	☒ Y ☒ N	☒ Y ☒ N	☒ Y ☒ N	Type of Fluid
Gas or Oil	☒ Y ☒ N	☒ Y ☒ N	☒ Y ☒ N	☒ Y ☒ N	Injected for
Water	☒ Y ☒ N	☒ Y ☒ N	☒ Y ☒ N	☒ Y ☒ N	Waterflood if
					applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

BS 4/01/2015

Signature: 	OIL CONSERVATION DIVISION
Printed name: Alex Estrella	Entered into RBDMS
Title: Production Tech	Re-test
E-mail Address: alex_estrella@oxy.com	
Date:	
Phone: 575-390-9889	
Witness: 	

INSTRUCTIONS ON BACK OF THIS FORM

APR 02 2015