

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

19
APR 3 2015

BRADENHEAD TEST REPORT

RECEIVED

Operator Name Chevron	API Number 30-025-25724
Property Name CVU	Well No. 58

Surface Location

UL - Lot A	Section 36	Township 17	Range 34	☒	Feet from 1310	N/S Line N	Feet From 132	E/W Line E	County LCA
----------------------	----------------------	-----------------------	--------------------	-------------------------------------	--------------------------	----------------------	-------------------------	----------------------	----------------------

Well Status

TA'D WELL YES ☒ NO	SHUT-IN YES ☒ NO	INJECTOR INJ ☒ SWD	PRODUCER OIL ☒ GAS	DATE 3/23/15
--	--	--	--	------------------------

OBSERVED DATA

	(A) Surface	(B) Interm(1)	(C) Interm(2)	(D) Prod Csg	(E) Tubing
Pressure	0	N/A	N/A	0	1950
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	CO2 ☒
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR ☒
Surges	Y/N	Y/N	Y/N	Y/N	GAS ☒
Down to nothing	Y/N	Y/N	Y/N	Y/N	Type of Fluid
Gas or Oil	Y/N	Y/N	Y/N	Y/N	Injected for
Water	Y/N	Y/N	Y/N	Y/N	Waterflood if applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

BS 4/8/2015

Signature: T. [Signature]	Chevron	OIL CONSERVATION DIVISION
Printed name:		Entered into RBDMS
Title:		Re-test
E-mail Address:		
Date: 3/23/15	Phone: 3904449	
Witness: [Signature]		

INSTRUCTIONS ON BACK OF THIS FORM

APR 14 2015