

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

APR 7 2015

BRADENHEAD TEST REPORT

RECEIVED

Operator Name DKD	API Number 30-025-27886 ✓
Property Name Richardson Fee SWD	Well No. 2 ✓

7. Surface Location

UL - Lot K	Section 5	Township 14S	Range 36E	Feet from 1980	N/S Line 5	Feet From 1980	E/W Line N	County Lea ✓
----------------------	---------------------	------------------------	---------------------	--------------------------	----------------------	--------------------------	----------------------	------------------------

Well Status

TA'D WELL YES ☐ NO ☒	SHUT-IN YES ☐ NO ☒	INJECTOR INJ ☐ SWD ☒	OIL PRODUCER OIL ☐ GAS ☐	DATE 4/2/15
--	--	--	---	-----------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	0	N/A	N/A	0	VACUUM
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	CO2 ☐
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR ☒
Surges	Y/N	Y/N	Y/N	Y/N	GAS ☐
Down to nothing	Y/N	Y/N	Y/N	Y/N	Type of Fluid
Gas or Oil	Y/N	Y/N	Y/N	Y/N	Injected for
Water	Y/N	Y/N	Y/N	Y/N	Waterflood if applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

B8 4/7/2015

Signature: Danny R Watson	OIL CONSERVATION DIVISION
Printed name: DANNY R WATSON	Entered into RBDMS
Title: OWNER	Re-test
E-mail Address:	
Date: 4/2/15	Phone:
Witness: Joe Brown	

INSTRUCTIONS ON BACK OF THIS FORM

APR 14 2015