

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

APR 7 2015

RECEIVED

BRADENHEAD TEST REPORT

Operator Name DKD	API Number 30-025-34197
Property Name WATSON 6	Well No. 1

Surface Location

UL - Lot N	Section 6	Township 16S	Range 36E	Feet from 2857	N/S Line S	Feet From 1417	E/W Line W	County DOA
----------------------	---------------------	------------------------	---------------------	--------------------------	----------------------	--------------------------	----------------------	----------------------

Well Status

TA'D WELL YES ☒ NO	SHUT-IN YES ☒ NO	INJECTOR INJ ☒ SWD	PRODUCER OIL ☒ GAS	DATE 4/2/15
--	--	--	--	-----------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	9	2/A	2/A	0	1/2" x 1/2"
Flow Characteristics					
Pull	Y/N	Y/N	Y/N	Y/N	CO2 ☐
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR ☐
Surges	Y/N	Y/N	Y/N	Y/N	GAS ☐
Down to nothing	0/N	Y/N	Y/N	Y/N	Type of Fluid
Gas or Oil	Y/N	Y/N	Y/N	Y/N	Injected for
Water	Y/N	Y/N	Y/N	Y/N	Waterflood if
					applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

BS 4/7/2015

Signature: Danny R Watson	OIL CONSERVATION DIVISION
Printed name: DANNY R WATSON	Entered into RBDMS
Title: OWNER	Re-test
E-mail Address:	
Date: 4/2/15	Phone:
Witness: Gregg Bow	

INSTRUCTIONS ON BACK OF THIS FORM

APR 14 2015