

APR 30 2015

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

Operator Name Linn Operating	API Number 30-025-01525
Property Name Caprock Maljamar Unit	Well No. 98

7. Surface Location

UL - Lot M	Section 28	Township 17s	Range 33E	Feet from 660	N/S Line FSL	Feet From 660	E/W Line FWL	County Lea
----------------------	----------------------	------------------------	---------------------	-------------------------	------------------------	-------------------------	------------------------	----------------------

Well Status

TA'D WELL YES	NO	SHUT-IN YES	NO	INJECTOR INJ	SWD	OIL	PRODUCER GAS	DATE 4/28/15
------------------	----	-----------------------	----	------------------------	-----	-----	-----------------	------------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	0	N/A	N/A	300	1800
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	CO2 —
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR ✓
Surges	Y/N	Y/N	Y/N	Y/N	GAS —
Down to nothing	Y/N	Y/N	Y/N	Y/N	Type of Fluid
Gas or Oil	Y/N	Y/N	Y/N	Y/N	Injected for
Water	Y/N	Y/N	Y/N	Y/N	Waterflood if
					applies.

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Well is S.I. Due to Tbg or PKR leak

A-O, Nothing

D-3001b, water, steady flow

Failure ✓

BS 5/5/2015

Signature: D. Sooter	OIL CONSERVATION DIVISION
Printed name: Darren Sooter	Entered into RBDMS
Title: Production Specialist	Re-test
E-mail Address: dsooter@linenergy.com	
Date: 4/28/15	Phone: 575-364-9113
Witness:	

INSTRUCTIONS ON BACK OF THIS FORM

MAY 13 2015

[Handwritten signature]