

HOBBS OCD

MAY 15 2015

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

Operator Name Apache Corp	API Number 30-025-05770
Property Name NMGSAU	Well No. 1511

Surface Location

UT. - Lot K	Section 31	Township 19S	Range 37E	Feet from 2310	N/S Line S	Feet from 2310	E/W Line W	County Lee
-----------------------	----------------------	------------------------	---------------------	--------------------------	----------------------	--------------------------	----------------------	----------------------

Well Status

TA'D WELL YES	NO	SHUT-IN YES	NO	INJECTOR (INJ)	SWD	OIL	PRODUCER GAS	DATE 5-5-15
------------------	----	----------------	----	--------------------------	-----	-----	-----------------	-----------------------

OBSERVED DATA

	(A)Surface	(B)Intern(1)	(C)Intern(2)	(D)Prod Casing	(E)Tubing
Pressure				0	715
Flow Characteristics					
Pull	(Y) N	Y / N	Y / N	Y / N	CO2
Steady Flow	Y / N	Y / N	Y / N	Y / N	WTR ☒
Surges	Y / N	Y / N	Y / N	Y / N	GAS
Down to nothing	(Y) N	Y / N	Y / N	Y / N	Type of fluid injected for Waterflood if applies
Gas or Oil	Y / N	Y / N	Y / N	Y / N	
Water	Y / N	Y / N	Y / N	Y / N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

FOR RECORD ONLY

B8 5/22/2015

Signature: Jim Ellison	OIL CONSERVATION DIVISION
Printed name: Jim Ellison	Entered into RBDMS
Title: Instrument Tech	Re-test
E-mail Address: J.D.Ellison @ apache corp.com	
Date:	Phone: 575-441-7734
Witness:	

INSTRUCTIONS ON BACK OF THIS FORM

MAY 27 2015