<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240 Phone: (575) 393-6161 Fax: (575) 393-0720

HOBBS OCD

State of New Mexico Energy, Minerals and Natural Resources Department Oil Conservation Division Hobbs District Office

MAY 2 6 2015

				BRADEN	HEAD TE	ST RF	PORT			VECE	N E ()	
Property Name SKELLY PENROSE B UNIT									. API Number			
									30-025-10627 Well No.			
									17 well No.			
				^{7.} S	urface Locati	on					-	
UL - Lot Section To		Township 23S	Range 37E		Feet from 660	N/S Line NORTH		Feet From 660		E/W Line WEST	Count LEA	
				1	Well Status	i						
Well Status			SHUT-IN		PRODUCING A - INJ			DATE 04/23/20				
hradanhea				TERMEDIATE 1			<u> </u>		_	ES EACH		
DIAGCIIBCA	Howed wa		heck all of the descriptions that (A)Surf-Interm (B)		_		(C)Interm-Prod		(D)Prod Csng		(E)Tubing	
ressure			<u>0#</u>			-			125		410	
ow Chara	cteristics					 				 .		
Puf	<u> </u>		N	Y	/ N	 	Y / N			Υ	_	
Steady Flow		 -	Y/N	Y	7 N		Y/N		_			
Surges			Y / N	Y	7 N	 						
Down to nothing			Y / N	Y	/ N	Y/N			<u> </u>	Y		
Gas or Oil		<u> </u>	Y/N	Y	/ N	Y/N			N		-	
Water			Y/N	Y	7 N	┨	Y / N			Υ		
bradenhead flowed water, LEAR			heck all of the descriptions that appl FRESH		SALTY		SULFUR			BLACK		
emarks:											,	
)) Prod Cas	ng: Casing	had black en	nulsion at valve	. Cracked casing v	valve - blew dow	n in 8 - 10		or R	ecc	rd or		
)) Prod Cas	ng: Casing	had black en	nulsion at valve	. Cracked casing v	valve - blew dow	n in 8 - 10				ORD ON		
	ng: Casing	had black en	nulsion at valve	. Cracked casing v	valve - blew dow	n in 8 - 10		<i>[</i>	3 5	126/20	0/5	
ignature:			nulsion at valve	. Cracked casing v	valve - blew dow	n in 8 - 10		OII	S S	(26/20 SERVATIO		
rignature:	e: C. DALE		nulsion at valve	. Cracked casing v	valve - blew dow	n in 8 - 10		OII	S S	(26/20 SERVATIO	0/5	
ignature:	e: C. DALE	KELTON		. Cracked casing v	valve - blew dow	n in 8 - 10		OII	S S	(26/20 SERVATIO	0/5	
Signature: Printed name	C. DALE	KELTON	suddenlink.net		valve - blew dow	n in 8 - 10		OII	S S	(26/20 SERVATIO	0/5	