District I 1625 N. French Dr., Hobbs, NM 88240 District II 811 S. First St., Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505 State of New Mexico Energy Minerals and Natural Resources

> Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

Form C-129 Revised August 1, 2011

Submit one copy to appropriate District Office

NFO Permit No.

.

(For Division Use Only)

APPLICATION FOR EXCEPTION TO NO-FLARE RULE 19.15.18.1	APPLICATION FOR EXCEPTION TO NO-FL	LARE RULE 19.15.18.12
---	------------------------------------	-----------------------

(See Rule 19.15.18.12 NMAC and Rule 19.15.7.37 NMAC)				
		HOBBSOCD		
А.	Applicant <u>Murchison Oil & Gas, Inc.</u>	JUN 1.7 2015		
	whose address is7250 Dallas Parkway, Ste. 1400, Plano, TX 75024			
	hereby requests an exception to Rule 19.15.18.12 for days or	until,		
	, Yr, for the following described tank battery (or LACT):			
	Name of Lease Jackson Unit 19H (30-025-41138) Name of Pool Triple X; Bone Spring, West			
	Location of Battery: Unit Letter <u>N</u> Section <u>21</u> Township <u>24S</u> Rang	e <u>33E</u>		
	Number of wells producing into battery <u>1</u>			
B.	Based upon oil production ofbarrels per day, the estimated * v	olume		
	of gas to be flared is75MCF; Value\$188per	day.		
C.	Name and location of nearest gas gathering facility:			
	Frac Cat Compressor Station, Lea County, NM			
D.	DistanceEstimated cost of connection			
E.	This exception is requested for the following reasons: Intermittent curtailment by Agar compressor maintenance. Well shut in at this time may damage formation and reduce			
OPERATOR	OIL CONSERVATION DIVISION			
	hat the rules and regulations of the Oil Conservation en complied with and that the information given above lete to the best of my knowledge and belief	015		
	hat the rules and regulations of the Oil Conservation en complied with and that the information given above lete to the best of my knowledge and belief. Mad 20B			
Signature		ر ر		
Printed Name		visor		

Date

 Date
 6/15/15
 Telephone No.
 972-931-0700

 *
 Gas-Oil ratio test may be required to verify estimated gas volume.

Email Address rcooper@jdmii.com

6