

JUL 01 2015

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

Operator Name Chevron USA Inc	API No. 30-025-23944
Property Name NVAWU	Well No. 14

Surface Location									
B	Section 28	Township 17S	Range 34E	Foot from 660	Line N	Foot from 1980	FWL E	County Lea	


Well Status									
PROD WELL YES	☒ NO	SHUT IN YES	☒ NO	INJ YES	SWD YES	☒ OIL	PRODUCER GAS	DATE 6-4-15	

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod C.Sug	(E)Tubing
Pressure	NA	NA	NA	40	400
Flow Characteristics					
Pull	Y / N	Y / N	Y / N	Y / ☒	CO2 ___
Steady Flow	Y / N	Y / N	Y / N	Y / ☒	WTR ___
Surges	Y / N	Y / N	Y / N	Y / ☒	GAS ___
Down to nothing	Y / N	Y / N	Y / N	Y / N	Type of Fluid
Gas or Oil	Y / N	Y / N	Y / N	Y / ☒	Injected for
Water	Y / N	Y / N	Y / N	Y / ☒	Waterflood if applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

BS 7/10/2015

Signature: 	OIL CONSERVATION DIVISION
Printed name: Linda Robinson	Entered into RBDMS
Title: FS B	Re-test
E-mail Address: LROU@Chevron.com	
Date: 6-4-15	Phone: 575 704 2225

JUL 13 2015

ALL INFORMATION ON BACK OF THIS FORM