

JUL 01 2015

RECEIVED

BRADENTHEAD TEST REPORT

Operator Name	USA Inc	Well No	30-025-24019
Property Name	NVAWA	Lea	11

Surface Location									
P	21	17	34	640	S	660	E	Lea	Lea

Well Status									
YES	TVD WELL	NO	YES	NO	NO	NO	NO	NO	NO

OBSERVED DATA

	(A) Surface	(B) Intermt(1)	(C) Intermt(2)	(D) Prod Casing	(E) Tubing
Pressure	80			80	60
Flow Characteristics					
Pull	Y / N	Y / N	Y / N	Y / N	CO2
Steady Flow	Y / N	Y / N	Y / N	Y / N	WTR
Surges	Y / N	Y / N	Y / N	Y / N	GAS
Down to nothing	Y / N	Y / N	Y / N	Y / N	Type of Fluid
Gas or Oil	Y / N	Y / N	Y / N	Y / N	Injected for
Water	Y / N	Y / N	Y / N	Y / N	Watered if applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

BS 7/10/2015

Signature: Linda Robinson	OIL CONSERVATION DIVISION
Printed name: Linda Robinson	Entered into RDBMS
Title: FS B	Re-test
E-mail Address: LROU@Chevron.com	
Date: 6-8-15	
Phone: 975 704 2225	

JUL 13 2015