

JUL 01 2015

State of New Mexico  
 Energy, Minerals and Natural Resources Department  
 Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

|                                 |                       |                                     |
|---------------------------------|-----------------------|-------------------------------------|
| Operator Name<br><b>Chevron</b> | USA Inc               | API Number<br><b>30025240500000</b> |
| Property Name<br><b>NVAWU</b>   | Well No.<br><b>23</b> |                                     |

Surface Location

|                      |                      |                        |                     |                         |                      |                         |                      |                      |
|----------------------|----------------------|------------------------|---------------------|-------------------------|----------------------|-------------------------|----------------------|----------------------|
| UL - Lot<br><b>D</b> | Section<br><b>34</b> | Township<br><b>19S</b> | Range<br><b>34E</b> | Feet from<br><b>510</b> | N-S Line<br><b>N</b> | Feet From<br><b>460</b> | F/W Line<br><b>W</b> | County<br><b>Lea</b> |
|----------------------|----------------------|------------------------|---------------------|-------------------------|----------------------|-------------------------|----------------------|----------------------|

Well Status

|                  |           |                |           |            |                 |            |                 |                       |
|------------------|-----------|----------------|-----------|------------|-----------------|------------|-----------------|-----------------------|
| TA'D WELL<br>YES | <b>NO</b> | SHUT-IN<br>YES | <b>NO</b> | INJ<br>INJ | INJECTOR<br>SWD | <b>OIL</b> | PRODUCER<br>GAS | DATE<br><b>6-6-15</b> |
|------------------|-----------|----------------|-----------|------------|-----------------|------------|-----------------|-----------------------|

OBSERVED DATA

|                      | (A)Surface   | (B)Interm(1) | (C)Interm(2) | (D)Prod Casing | (E)Tubing                                        |
|----------------------|--------------|--------------|--------------|----------------|--------------------------------------------------|
| Pressure             | <b>20</b>    | --           |              | <b>10</b>      | <b>60</b>                                        |
| Flow Characteristics |              |              |              |                |                                                  |
| Puff                 | <b>Y / N</b> | <b>Y / N</b> | <b>Y / N</b> | <b>Y / N</b>   | CO2 ___                                          |
| Steady Flow          | <b>Y / N</b> | <b>Y / N</b> | <b>Y / N</b> | <b>Y / N</b>   | WTR ___                                          |
| Surges               | <b>Y / N</b> | <b>Y / N</b> | <b>Y / N</b> | <b>Y / N</b>   | GAS ___                                          |
| Down to nothing      | <b>Y / N</b> | <b>Y / N</b> | <b>Y / N</b> | <b>Y / N</b>   | Type of fluid injected for waterflood if applies |
| Gas or Oil           | <b>Y / N</b> | <b>Y / N</b> | <b>Y / N</b> | <b>Y / N</b>   |                                                  |
| Water                | <b>Y / N</b> | <b>Y / N</b> | <b>Y / N</b> | <b>Y / N</b>   |                                                  |

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Well is down for hole in tubing. Surface casing bled down to 5 psi and stayed there

BR 7/10/2015

Signature

*Linda Robinson*

OIL CONSERVATION DIVISION

Printed name

Linda Robinson

Entered into RUDMS

Field Specialist

Revised

Field Address

28400 Chevron Circle

Date 6-6-15

575 724-2225

JUL 13 2015

*[Signature]*