

HOBBS OCD

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

JUL 01 2015

BRADENHEAD TEST REPORT

RECEIVED

Operator Name Chervon USA Inc	30-025-24064
Property Name NVAWU	9

Surface Location

Section L	Section 22	Section 17 S	Section 34 E	Foot from 1874	Section S	Foot from 766	Section W	Section 6 ea
---------------------	----------------------	------------------------	------------------------	--------------------------	---------------------	-------------------------	---------------------	------------------------

Well Status

YES	TVD WELL NO	YES	SHEATH NO	INJ	INJECTOR NO	SWD	PRODUCT OIL	GAS	DATE 6-4-15
-----	-----------------------	-----	---------------------	-----	-----------------------	-----	-----------------------	-----	-----------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csmg	(E)Tubing
Pressure	0	0		50	400
Flow Characteristics					
Pull	Y/N	Y/N	Y/N	Y/N	CO2 ___
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR ___
Surges	Y/N	Y/N	Y/N	Y/N	GAS ___
Down to nothing	Y/N	Y/N	Y/N	Y/N	Type of Fluid
Gas or Oil	Y/N	Y/N	Y/N	Y/N	Injected for
Water	Y/N	Y/N	Y/N	Y/N	Water shed if
					applies

Remarks -- Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

BB 7/10/2015

Signature Linda Robinson	OIL CONSERVATION DIVISION
Printed name Linda Robinson	Entered into RBDMS
Title FS B	Re-test
E-mail Address LROU@Chervon.com	
Date 6-4-15	Phone 575 704 2225

JUL 13 2015

ATTACH IN BACK OF THIS FORM