

JUL 01 2015

State of New Mexico
 Energy, Minerals and Natural Resources Department
 Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

Operator Name Chevron USA Inc	API Number 30-025-24112
Property Name NVAWU	Well No. 5

Surface Location

UL - Lot D	Section 22	Township 17S	Range 34E	Feet from 660	N-S Line N	Feet from 660	E-W Line W	County Lea
----------------------	----------------------	------------------------	---------------------	-------------------------	----------------------	-------------------------	----------------------	----------------------

Well Status

TA'D WELL ☒ YES	NO	SHUT-IN ☒ YES	NO	INJECTOR ☒ INJ	SWD	OIL	PRODUCER	GAS	DATE 6-4-15
--	----	--	----	---	-----	-----	----------	-----	-----------------------

OBSERVED DATA

	(A) Surface	(B) Interm(1)	(C) Interm(2)	(D) Prod. Casing	(E) Tubing
Pressure	0	NA	NA	0	0
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	CO2
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR
Surges	Y/N	Y/N	Y/N	Y/N	GAS
Down to nothing	Y/N	Y/N	Y/N	Y/N	Type of fluid injected for waterflood if applies
Gas or Oil	Y/N	Y/N	Y/N	Y/N	
Water	Y/N	Y/N	Y/N	Y/N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

BS 7/10/2015

Signature **Linda Robinson**

Printed name **Linda Robinson**

Title **Field Specialist**

Phone Area **214** **222-2225**

Date **6-4-15**

Phone **575 724-2225**

OIL CONSERVATION DIVISION

Hobbs District Office

Room

JUL 13 2015