

JUL 01 2015

RECEIVED

LEAK DETECTION TEST REPORT

Chevron
Central Vacuum Unit30-025-25721 -
55 -

Surface Location

D 36 T175 R348

Lea

Well Status

AP	BP	CP	DP	EP	FP	GP	HP	IP	JP	KP	LP	MP	NP	OP	PP	QP	RP	SP	TP	UP	VP	WP	XP	YP	ZP

6-2/2015

OBSERVED DATA

	(A)Surface	(B)Intern1	(C)Intern2	(D)Prod Casing	(E)Tubing
Pressure	Ø	N/A	N/A	Ø	1800
Flow Characteristics					
Pull	Y/N	Y/N	Y/N	Y/N	CO2
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR X
Surges	Y/N	Y/N	Y/N	Y/N	GAS
Down to nothing	Y/N	Y/N	Y/N	Y/N	Type of Fluid
Gas or Oil	Y/N	Y/N	Y/N	Y/N	Injected fluid
Water	Y/N	Y/N	Y/N	Y/N	Water level if applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

BS 7/10/2015

Signature: <i>[Signature]</i>	OIL CONSERVATION DIVISION
Printed name: EDDIE GALLER	Entered into RBDMS
Title: 5515	Re-test
Phone: 515-631-8516	
Date: 6/3/15	

JUL 14 2015