

HOBBS OCD

JUN 19 2015

RECEIVED

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name Chevron	API Number 30-025-02226 ✓
Property Name VGSAU	Well No. VGSAU 66 ✓

Surface Location

Bl. - Lot L	Section 35	Township 17S	Range 34E	Feet from 1980	N/S Line 1/5	Feet from 100	E/W Line W	County LEA
-----------------------	----------------------	------------------------	---------------------	--------------------------	------------------------	-------------------------	----------------------	----------------------

Well Status

TAD WELL YES	<input checked="" type="checkbox"/> NO	SHUT-IN YES	<input checked="" type="checkbox"/> NO	INJECTOR INJ	SWD	<input checked="" type="radio"/> OIL	PRODUCER GAS	DATE 5-27-15
-----------------	--	----------------	--	-----------------	-----	--------------------------------------	-----------------	------------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	0	NA	NA	0	280
Flow Characteristics					
Puff	Y/X	Y/N	Y/N	Y/X	CO2 <input type="checkbox"/>
Steady Flow	Y/X	Y/N	Y/N	Y/X	WTR <input type="checkbox"/>
Surges	Y/X	Y/N	Y/N	Y/X	GAS <input type="checkbox"/>
Down to nothing	Y/X	Y/N	Y/N	Y/X	Type of Fluid
Gas or Oil	Y/X	Y/N	Y/N	Y/X	Injected for
Water	Y/X	Y/N	Y/N	Y/X	Water, if it applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

BS 6/30/2015

Signature: A-L P	OIL CONSERVATION DIVISION
Printed name: Austin Pogue	Entered into RBDMS
Title: FSA	Re-test
Email Address: atym@chevron.com	
Date: 5-27-15	Phone: 575-513-0363

JUL 15 2015

[Handwritten mark]