

JUN 19 2015

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

Operator Name Churron	API Number 30-025-02247
Property Name UGSAU	Well No. 43

* Surface Location

GLS Lot H	Section 41	Township 18S	Range 34E	Feet from 1980	NS Line N	Feet from 484	E/W Line E	County Log
---------------------	----------------------	------------------------	---------------------	--------------------------	---------------------	-------------------------	----------------------	----------------------

Well Status


TAB WELL YES	☒ NO	SHUT-IN YES	☒ NO	INJ	INJECTOR SWD	☒ OIL	PRODUCER GAS	DATE 5-28-15
-----------------	-------------------------------------	----------------	-------------------------------------	-----	-----------------	--------------------------------------	-----------------	------------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Casing	(E)Tubing
Pressure	0			190	240
Flow Characteristics					
Pull	☒ Y ☒ N	☐ Y ☐ N	☐ Y ☐ N	☒ Y ☒ N	CO2 ☐
Steady Flow	☒ Y ☒ N	☐ Y ☐ N	☐ Y ☐ N	☒ Y ☒ N	WTR ☐
Surges	☒ Y ☒ N	☐ Y ☐ N	☐ Y ☐ N	☒ Y ☒ N	GAS ☐
Down to nothing	☒ Y ☒ N	☐ Y ☐ N	☐ Y ☐ N	☒ Y ☒ N	Type of fluid injected for Water: ☐ If applies
Gas or Oil	☒ Y ☒ N	☐ Y ☐ N	☐ Y ☐ N	☒ Y ☒ N	
Water	☒ Y ☒ N	☐ Y ☐ N	☐ Y ☐ N	☒ Y ☒ N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

B8 6/30/2015

Signature: 	OIL CONSERVATION DIVISION
Printed name: Austin Poyne	Entered into RBDMS
Title: FSA	Re-test
E-mail Address: etym@chevron.com	
Date: 5-28-15	Phone: 575-513-0363

JUL 15 2015

f