

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

JUN 19 2015

RECEIVED

BRADENHEAD TEST REPORT

Operator Name Churton	API Number 30-025-02248
Property Name UGSAU	Well No. 57

Surface Location

GL - Lot B	Section 21	Township 18S	Range 34E	Feet from 660'	N/S Line N	Feet from 1980'	E/W Line E	County Lea
----------------------	----------------------	------------------------	---------------------	--------------------------	----------------------	---------------------------	----------------------	----------------------

Well Status


TAB WELL YES ☒	SHUT-IN YES ☒	INJ YES ☒	INJECTOR SWD ☒	PRODUCER OIL	GAS ☒	DATE 5-28-15
---	--	--	---	------------------------	---	------------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Casing	(E)Tubing
Pressure	0	NA	NA	0	220
Flow Characteristics					
Pull	Y / X	Y / N	Y / N	Y / X	CO2 ☐
Steady Flow	Y / X	Y / N	Y / N	Y / X	WTR ☐
Surges	Y / X	Y / N	Y / N	Y / X	GAS ☐
Down to nothing	Y / X	Y / N	Y / N	Y / X	Type of fluid
Gas or Oil	Y / X	Y / N	Y / N	Y / X	Injected for
Water	Y / X	Y / N	Y / N	Y / X	Water used if applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

BS 6/30/2015-

Signature: 	OIL CONSERVATION DIVISION
Printed name: Austin Payne	Entered into RBDMS
Title: BSA	Re-test
Email Address: etymachurton.com	
Date: 5-28-15	Phone: 575 513 0363

JUL 15 2015