

JUN 19 2015

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

Operator Name Chawron	API Number 30-025-02251
Property Name VGSAU	Well No. VGSAU 56

Surface Location

1/4 - Lot C	Section 1	Township 18S	Range 34E	Feet from WTL	N/S Line N	Feet from 1980	E/W Line W	County LEA
-----------------------	---------------------	------------------------	---------------------	-------------------------	----------------------	--------------------------	----------------------	----------------------

Well Status

TA'D WELL YES	SHUT-IN NO	INJECTOR NO	PRODUCER OIL	DATE 5-27-15
-------------------------	----------------------	-----------------------	------------------------	------------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	0 NA	NA		0	220
Flow Characteristics					
Puff	Y / X	Y / X	Y / N	Y / N	CO2 ___
Steady Flow	Y / X	Y / X	Y / N	Y / N	WTR ___
Surges	Y / X	Y / X	Y / N	Y / N	GAS ___
Down to nothing	Y / X	Y / X	Y / N	Y / N	Type of fluid
Gas or Oil	Y / X	Y / X	Y / N	Y / N	Injected for
Water	Y / X	Y / X	Y / N	Y / N	Water flow if
					applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

BS 6/30/2015

Signature: <i>Austin Pague</i>	OIL CONSERVATION DIVISION
Printed name: Austin Pague	Entered into RBDMS
Title: FSA	Re-test
E-mail Address: etym@chevron.com	
Date: 5-27-15	Phone: 575-513-0363

JUL 15 2015

K