

JUN 19 2015

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

Operator Name Chevron	API Number 30-025-02252 <i>L</i>
Property Name VGSAN	Well No. 40

Surface Location

Block	Section	Township	Range	Feet from	NS Line	Feet from	EW Line	County
E	101	18S	34E	1980	N	660	W	CEA <i>L</i>

Well Status

TA'D WELL YES	NO	SHUT-IN YES	NO	INJ INJ	SWD SWD	PRODUCER OIL	GAS GAS	DATE 5-28-15
------------------	-----------	----------------	-----------	------------	------------	------------------------	------------	------------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Casing	(E)Tubing
Pressure	0			110	290
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	CO2 <i>___</i>
Steady Flow	Y / N	Y / N	Y / N	Y / N	WTR <i>___</i>
Surges	Y / N	Y / N	Y / N	Y / N	GAS <i>___</i>
Down to nothing	Y / N	Y / N	Y / N	Y / N	Type of Fluid
Gas or Oil	Y / N	Y / N	Y / N	Y / N	Injected for
Water	Y / N	Y / N	Y / N	Y / N	Waterch... if applies

Remarks – Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

BS 6/30/2015

Signature: <i>Austin Roque</i>	OIL CONSERVATION DIVISION
Printed name: Austin Roque	Entered into RBDMS
Title: PSA	Re-test
Email Address: etym@chevron.com	
Date: 5-28-15	Phone: 575 513 0363

JUL 15 2015

4