

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

JUN 19 2015

RECEIVED

BRADENHEAD TEST REPORT

Operator Name Chexon	API Number 30-025-02258 L
Property Name VCSA	Well No. 10 L

2. Surface Location

BL - Lot M	Section 1	Township 19S	Range 34E	Feet from WED	N/S Line S	Feet from WED	E/W Line N	County LEA ✓
----------------------	---------------------	------------------------	---------------------	-------------------------	----------------------	-------------------------	----------------------	-------------------------------

Well Status

TAB WELL YES	NO	SHUT-IN YES	NO	INJ INJ	SWD SWD	OH	PRODUCER GAS	DATE 5-28-15
-----------------	-----------	----------------	-----------	------------	------------	-----------	-----------------	------------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Casing	(E)Tubing
Pressure	0			20	50
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	CO2 —
Steady Flow	Y / N	Y / N	Y / N	Y / N	WTR —
Surges	Y / N	Y / N	Y / N	Y / N	GAS —
Down to nothing	Y / N	Y / N	Y / N	Y / N	Type of Fluid Injected for
Gas or Oil	Y / N	Y / N	Y / N	Y / N	Water 3-4 ft applies
Water	Y / N	Y / N	Y / N	Y / N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

B8 7/1/2015

Signature: 	OIL CONSERVATION DIVISION
Printed name: Austin Regue	Entered into RRDMS
Title: PSA	Re-test
Email Address: etm@chexon.com	
Date: 5-28-15	Phone: 575-513-0363

JUL 15 2015

