

JUN 19 2015

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

Operator Name Churron	API Number 30-025-02266
Property Name	Well No. V63AU 51

2. Surface Location

GL - Lat D	Section 2	Township 18S	Range 34E	Feet from Well	N/S Line N	Feet from Well	E/W Line N	County LEA
----------------------	---------------------	------------------------	---------------------	--------------------------	----------------------	--------------------------	----------------------	----------------------

Well Status

TA'D WELL YES	SHUT-IN YES	INJ NO	INJECTOR SWD	PRODUCER GAS	DATE 5-27-15
------------------	----------------	-----------	-----------------	-----------------	------------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Casing	(E)Tubing
Pressure	0	NA	NA	40	50
Flow Characteristics					
Puff	Y / X	Y / N	Y / N	Y / X	CO2 ☐
Steady Flow	Y / X	Y / N	Y / N	Y / X	WTR ☐
Surges	Y / X	Y / N	Y / N	Y / X	GAS ☐
Down to nothing	Y / X	Y / N	Y / N	Y / X	Type of Fluid
Gas or Oil	Y / X	Y / N	Y / N	Y / X	Injected f.e
Water	Y / X	Y / N	Y / N	Y / X	Waterlogged if applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

BS 6/30/2015

Signature: A-22	OIL CONSERVATION DIVISION
Printed name: Austin Pogue	Entered into RHDBMS
Title: FSA	Re-test
Email Address: ctym@churron.com	
Date: 5-27-15	Phone: 575-513-0303

JUL 15 2015

h