

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

JUN 19 2015

BRADENHEAD TEST REPORT

RECEIVED

Operator Name Chevron	API Number 30-025-02275
Property Name VGSAU	Well No. #8

2. Surface Location

GL - Lat 0	Section 02	Township 18S	Range 34E	Feet from 000	N/S Line S	Feet from 1980	E/W Line E	County Lea
----------------------	----------------------	------------------------	---------------------	-------------------------	----------------------	--------------------------	----------------------	----------------------

Well Status


TAB WELL YES	SHUT-IN YES	INJ YES	INJECTOR SWD	PRODUCER GAS	DATE 5-28-15
-----------------	----------------	------------	-----------------	-----------------	------------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	0	NA	NA	60	150
Flow Characteristics					
Puff	Y / X	Y / N	Y / N	Y / X	CO2 ___
Steady Flow	Y / X	Y / N	Y / N	Y / X	WTR ___
Surges	Y / X	Y / N	Y / N	Y / X	GAS ___
Down to nothing	Y / X	Y / N	Y / N	Y / X	Type of fluid
Gas or Oil	Y / X	Y / N	Y / N	Y / X	Injected for
Water	Y / X	Y / N	Y / N	Y / X	Waterhold if
					applies

Remarks -- Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

B8 7/1/2015

Signature: 	OIL CONSERVATION DIVISION
Printed name: Austin Pague	Entered into RRDMS
Title: FSA	Re-test
Email Address: etym@chevron.com	
Date: 5-28-15	
Phone: 575 513 0363	

ACCEPTED BY: [Signature]

JUL 15 2015