

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

JUN 19 2015

RECEIVED

BRADENHEAD TEST REPORT

Operator Name Chevron	API Number 30-025-02277
Property Name UGSAU	Well No. #7

Surface Location

Pl. Lot N	Section 2	Township 718S	Range 34E	Feet from 660	N/S Line S	Feet from 1987	E/W Line W	County LEA
---------------------	---------------------	-------------------------	---------------------	-------------------------	----------------------	--------------------------	----------------------	----------------------

Well Status

TA'D WELL YES	NO	SHUT-IN YES	NO	INJECTOR INJ	SWD	PRODUCER OIL	GAS	DATE 5-28-15
------------------	-----------	----------------	-----------	-----------------	-----	------------------------	-----	------------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Casing	(E)Tubing
Pressure	0			30	310
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	CO2 ___
Steady Flow	Y / N	Y / N	Y / N	Y / N	WTR ___
Surges	Y / N	Y / N	Y / N	Y / N	GAS ___
Down to nothing	Y / N	Y / N	Y / N	Y / N	Type of Fluid
Gas or Oil	Y / N	Y / N	Y / N	Y / N	Injected for
Water	Y / N	Y / N	Y / N	Y / N	Water level if applies

Remarks -- Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

B8 7/1/2015

Signature A. 2R	OIL CONSERVATION DIVISION
Printed name Austin Pogue	Entered into RBDMS
Title PSA	Re-test
Email Address etym@chevron.com	
Date 5-28-15	Phone 575-513-0343

JUL 15 2015

NOTED BY: [Signature] DATE: [Signature]