

JUL 10 2015

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

Operator Name CHEVRON USA Inc	API Number 30-025-20665
Property Name VGWU	Well No. 71

* Surface Location

TR - Loc H	Section 35	Township T17S	Range R34E	Feet from 2180 2110	NS Line N	Feet from 660	E/W Line E	County LCA
----------------------	----------------------	-------------------------	----------------------	---	---------------------	-------------------------	----------------------	----------------------

Well Status


TA'D WELL YES	NO 0	SHT-IN YES	NO 0	INJ	SWD	PRODUCER OIL 0	GAS	DATE 5/20/15
------------------	-------------	---------------	-------------	-----	-----	--------------------------	-----	------------------------


OBSERVED DATA

	(A) Surface	(B) Interm(1)	(C) Interm(2)	(D) Prod Csg	(E) Tubing
Pressure	0	N/A	N/A	40	180
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	CO2 ___
Steady Flow	Y / N	Y / N	Y / N	Y / N	WTR ___
Surges	Y / N	Y / N	Y / N	Y / N	GAS ___
Down to nothing	Y / N	Y / N	Y / N	Y / N	Type of Fluid
Gas or Oil	Y / N	Y / N	Y / N	Y / N	Injected for
Water	Y / N	Y / N	Y / N	Y / N	Water flood if applies

Remarks -- Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

B8 7/14/2015

Signature: 	OIL CONSERVATION DIVISION
Printed name: ALEX CROSBY	Entered into RBDMS
Title: FS	Re-test
E-mail address: EBXF@CHEVRON.COM	
Date: 5/20/15	Phone: 575 513 5521



JUL 15 2015

