

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

JUL 10 2015

BRADENHEAD TEST REPORT

RECEIVED

Operator Name CHEURON USA INC	VPI Number 30-025-21637
Property Name UGWU	Well No. 87

Surface Location

TH	Lat	Section	Township	Range	Feet from	NS Line	Feet from	EW Line	County
	J	36	T 19 S	R 34 E	2090	S	2086	E	Lea

Well Status

TA'D WELL	SHUT-IN	INJECTOR	PRODUCER	DATE
YES (NO)	YES (NO)	INJ (NO)	GAS (NO)	5/20/15

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Casing	(E)Tubing
Pressure	Ø	Ø	N/A	50	110
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	CO2 —
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR —
Surges	Y/N	Y/N	Y/N	Y/N	GAS —
Down to nothing	Y/N	Y/N	Y/N	Y/N	Type of Fluid
Gas or Oil	Y/N	Y/N	Y/N	Y/N	Injected for
Water	Y/N	Y/N	Y/N	Y/N	Water level if
					applies

Remarks -- Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

BS 7/14/2015

Signature: Alex Crosby	OIL CONSERVATION DIVISION
Printed name: ALEX CROSBY	Entered into RBDMS
Title: FS	Re-test
E-mail Address: ECXFC@CHEURON.COM	
Date: 5/26/15	Phone: 575 513 5521
	Web

JUL 15 2015

R