

JUN 19 2015

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

Operator Name Chevron	API Number 30-025-30718 ✓
Property Name UGSAD	Well No. 158 ✓

Surface Location

Blk - Lot B	Section 1	Township 18S	Range 34E	Feet from W60	NS Line N	Feet from 1330	E-W Line E	County Lea
-----------------------	---------------------	------------------------	---------------------	-------------------------	---------------------	--------------------------	----------------------	----------------------

Well Status


TVD WELL YES	NO	SHUT-IN YES	NO	INJ INJ	INJECTOR SWD	PRODUCER OIL	GAS	DATE 5-28-15
-----------------	-----------	----------------	-----------	------------	-----------------	------------------------	-----	------------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	0	0		130	240
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	CO2 —
Steady Flow	Y / N	Y / N	Y / N	Y / N	WTR —
Surges	Y / N	Y / N	Y / N	Y / N	GAS —
Down to nothing	Y / N	Y / N	Y / N	Y / N	Type of Fluid
Gas or Oil	Y / N	Y / N	Y / N	Y / N	Injected for
Water	Y / N	Y / N	Y / N	Y / N	Water level if applies

Remarks – Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

BS 6/30/2015

Signature: 	OIL CONSERVATION DIVISION
Printed name: Austin Page	Entered into RBDMS
Title: FSA	Re-test
E-mail Address: etym@chevron.com	
Date: 5-28-15	Phone: 575-513-0363

JUL 15 2015

