

JUN 19 2015

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

Operator Name Chevron	APC Number 30-025-30754
Property Name	Well No. UGSAU 138H

7. Surface Location

GL - Lot F	Section 22	Township 18S	Range 34E	Feet from 1980	N/S Line N	Feet from 2583	E/W Line W	County LEA
----------------------	----------------------	------------------------	---------------------	--------------------------	----------------------	--------------------------	----------------------	----------------------

Well Status


TA'D WELL YES	SHUT-IN YES	INJ INJ	SWD SWD	PRODUCER OIL	GAS GAS	DATE 5-27-15
------------------	----------------	------------	------------	------------------------	------------	------------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Casing	(E)Tubing
Pressure	0	NA	NA	0	320
Flow Characteristics					
PoIT	Y / X	Y / N	Y / N	Y / X	CO2 —
Steady Flow	Y / X	Y / N	Y / N	Y / X	WTR —
Surges	Y / X	Y / N	Y / N	Y / X	GAS —
Down to nothing	Y / X	Y / N	Y / N	Y / X	Type of Fluid
Gas or Oil	Y / X	Y / N	Y / N	Y / X	Injected for
Water	Y / X	Y / N	Y / N	Y / X	Waterhold if applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

B2 6/30/2015

Signature 	OIL CONSERVATION DIVISION
Printed name Austin Pogue	Entered into RHDMs
Title FSA	Re-test
E-mail Address etym@chevron.com	
Date 5-27-15	Phone 575-513-0363

JUL 15 2015