

JUN 19 2015

RECEIVED

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name Chvron	API Number 30-025-30797
Property Name	Well No. VGSA 141

Surface Location

1/4 - Lot C E	Section 11	Township 18S	Range 34E	Feet from 1980	N/S Line N	Feet from 1309	E/W Line W	County LEA
-----------------------------	----------------------	------------------------	---------------------	--------------------------	----------------------	--------------------------	----------------------	----------------------

Well Status

TVD WELL YES	SURFAN YES	INJ NO	INJECTOR NO	SWD NO	PRODUCER OIL	GAS NO	DATE 5-27-15
-----------------	---------------	-----------	----------------	-----------	------------------------	-----------	------------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Casing	(E)Tubing
Pressure	0	NA	NA	140	400
Flow Characteristics					
Puff	Y / X	Y / N	Y / N	Y / X	CO2 ___
Steady Flow	Y / X	Y / N	Y / N	Y / X	WTR ___
Surges	Y / X	Y / N	Y / N	Y / X	GAS ___
Down to nothing	Y / X	Y / N	Y / N	Y / X	Type of fluid
Gas or Oil	Y / X	Y / N	Y / N	Y / X	Injected for
Water	Y / X	Y / N	Y / N	Y / X	Water do/d if
					applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

BS 6/30/2015

Signature: A. Payne	OIL CONSERVATION DIVISION
Print Name: Austin Payne	Entered into RBDMS
Title: FSA	Re-test
Email Address: citym@chevron.com	
Date: 5-27-15	Phone: 575-513-0363

JUL 15 2015