

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

HOBBS OCD

JUN 19 2015

BRADENHEAD TEST REPORT

Operator Name Chevron		RECEIVED 30-025-30800	
Property Name VGSAU		Well No. VGSAU 155	

Surface Location

BL - Lot A	Section 2	Township 18S	Range R34E	Feet from WED	NS Line N	Feet from 10	EAV Line E	County LEA
----------------------	---------------------	------------------------	----------------------	-------------------------	---------------------	------------------------	----------------------	----------------------

Well Status

TAB WELL YES	☒ NO	SHUT-IN YES	☒ NO	INJ	INJECTOR SWD	☒ OIL	PRODUCER GAS	DATE 5-27-15
-----------------	-------------------------------------	----------------	-------------------------------------	-----	-----------------	--------------------------------------	-----------------	------------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Casing	(E)Tubing
Pressure	0	NA		120	100
Flow Characteristics					
Puff	Y / X	Y / N	Y / N	Y / X	CO2 ☐
Steady Flow	Y / X	Y / N	Y / N	Y / X	WTR ☐
Surges	Y / X	Y / N	Y / N	Y / X	GAS ☐
Down to nothing	Y / X	Y / N	Y / N	Y / X	Type of Fluid
Gas or Oil	Y / X	Y / N	Y / N	Y / X	Injected Ice
Water	Y / X	Y / N	Y / N	Y / X	Water loss if applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

BS 6/30/2015

Signature: <i>A-20</i>	OIL CONSERVATION DIVISION
Printed name: Andrew Pogue	Entered into RBDMS
Title: FSA	Re-test
Email Address: etym@chevron.com	
Date: 5-27-15	Phone: 575-513-0363

JUL 15 2015