

JUN 19 2015

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

Operator Name Chevron	API Number 30-025-30844
Property Name UGSAD	Well No. 143

Surface Location

U/L - Lot H	Section 1	Township 18S	Range 34E	Feet From 1980'	N/S Line N	Feet From 1250'	E/W Line E	County Lea
-----------------------	---------------------	------------------------	---------------------	---------------------------	----------------------	---------------------------	----------------------	----------------------

Well Status

TAID WELL YES	SHUT-IN YES	INJ NO	INJECTOR NO	SWD NO	PRODUCER OIL	GAS NO	DATE 5-28-15
------------------	----------------	-----------	----------------	-----------	-----------------	-----------	------------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	0	0		200	260
Flow Characteristics					
Pull	Y / N	Y / N	Y / N	Y / N	CO2
Steady Flow	Y / N	Y / N	Y / N	Y / N	WTR
Surges	Y / N	Y / N	Y / N	Y / N	GAS
Down to nothing	Y / N	Y / N	Y / N	Y / N	Type of Fluid
Gas or Oil	Y / N	Y / N	Y / N	Y / N	Injected for
Water	Y / N	Y / N	Y / N	Y / N	Water if it applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

BS 6/30/2015

Signature:

AR

Printed name: **Austin Poque**Title: **FSA**Email Address: **etyma@chevron.com**Date: **5-28-15**Phone: **575-513-0363**

Fax:

OIL CONSERVATION DIVISION

Entered into RHDMS

Re-test

JUL 15 2015