

JUN 19 2015

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

Operator Name Chevron	API Number 30-025-30851
Property Name VGSAU	Well No. VGSAU 156

7. Surface Location

Section C	Section 1	Township 18S	Range 34E	Feet from 6660	N/S Line N	Feet from 1330	E/W Line W	County LEA
---------------------	---------------------	------------------------	---------------------	--------------------------	----------------------	--------------------------	----------------------	----------------------

Well Status

TEST WELL YES ☒	SHUT-IN YES ☒	INJ YES ☒	INJECTOR YES ☒	PRODUCER OIL	GAS YES ☒	DATE 5-27-15
--	--	--	---	------------------------	--	------------------------


OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Casing	(E)Tubing
Pressure	20	0	NA	180	190
Flow Characteristics					
Puff	Y/N	Y/X	Y/N	Y/X	CO2 ☐
Steady Flow	Y/X	Y/X	Y/N	Y/X	WTR ☐
Surges	Y/X	Y/X	Y/N	Y/X	GAS ☐
Down to nothing	Y/X	Y/X	Y/N	Y/X	Type of fluid
Gas or Oil	Y/X	Y/X	Y/N	Y/X	Injected for
Water	Y/X	Y/X	Y/N	Y/X	Waterhead if
					applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Small Puff Bleed to Opsi

BB 6/30/2015

Signature: 	OIL CONSERVATION DIVISION
Printed name: Austin Pogue	Entered into RBDMs
Title: FSA	Re-test
Email Address: etym@chevron.com	
Date: 5-27-15	Phone: 575-513-0863
Min. test	

JUL 15 2015

EXTRACTED FROM THE STATE OF NEW MEXICO