

JUL 10 2015

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

Operator Name Chercon USA Inc		API Number 30-025-31701
Property Name Vacuum Calorita West Unit		Well No. 2/0

1. Surface Location

UL - Lot 6	Section 25	Township 17N	Range 34E	Feet from 1590	N/S Line S	Feet From 2404	E/W Line W	County LEA
----------------------	----------------------	------------------------	---------------------	--------------------------	----------------------	--------------------------	----------------------	----------------------

Well Status

☒ YES	☐ NO	☒ YES	☐ NO	☒ INJ	☐ SWD	☐ OIL	☐ PRODUCER	☐ GAS	DATE 5/7/15
--------------------------------------	--------------------------	--------------------------------------	--------------------------	--------------------------------------	---------------------------	---------------------------	--------------------------------	---------------------------	-----------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	0	2/1	2/1	0	0
Flow Characteristics					
Pull	Y/N	Y/N	Y/N	Y/N	Y/N
Steady Flow	Y/N	Y/N	Y/N	Y/N	Y/N
Surges	Y/N	Y/N	Y/N	Y/N	Y/N
Down to nothing	Y/N	Y/N	Y/N	Y/N	Y/N
Gas or Oil	Y/N	Y/N	Y/N	Y/N	Y/N
Water	Y/N	Y/N	Y/N	Y/N	Y/N

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

BB 7/14/2015 -

Signature: Tanner Detman	OIL CONSERVATION DIVISION
Printed name: Tanner Detman	Entered into RBDMS
Title: FSA	Re-test
E-mail Address: Tanner.Detman@com	
Date: 5/7/15	
Phone:	
Witness: [Signature]	

INSTRUCTIONS ON BACK OF THIS FORM

JUL 15 2015