

JUN 19 2015

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

Operator Name Cherwon		API Number 30-025-31703 L	
Property Name Vacuum Colonia West Unit		Well No. 53 L	

2. Surface Location

BL - Lot N	Section 25	Township 1N	Range 34E	Feet from 215	N/S Line S	Feet From 2350	E/W Line N	County LEA ✓
----------------------	----------------------	-----------------------	---------------------	-------------------------	----------------------	--------------------------	----------------------	-------------------------------

Well Status

YES	T&D WELL NO	YES	SHUT-IN NO	INJ	INJECTOR NO	SWD	OIL	PRODUCER GAS	DATE 5-21-2015
-----	-----------------------	-----	----------------------	------------	-----------------------	-----	-----	-----------------	--------------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Casing	(E)Tubing
Pressure	0	N/A	N/A	0	0
Flow Characteristics					
Pull	Y / 0	Y / N	Y / N	Y / 0	CO2 — WTR X GAS — Type of Fluid Injected for Waterflood if applies.
Steady Flow	Y / 0	Y / N	Y / N	Y / 0	
Surges	Y / 0	Y / N	Y / N	Y / 0	
Down to nothing	0 / N	Y / N	Y / N	0 / N	
Gas or Oil	Y / 0	Y / N	Y / N	Y / 0	
Water	Y / 0	Y / N	Y / N	Y / 0	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

B8 7/1/2015

Signature: Terry Cherwon	OIL CONSERVATION DIVISION
Printed name: Tanner Dutton	Entered into RBDMS
Title: FS	Re-test
E-mail Address: T244 @ cherwon.com	
Date:	Phone:
	Witness:

INSTRUCTIONS ON BACK OF THIS FORM

JUL 15 2015