

HOBBS OCD

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

JUL 10 2015

BRADENHEAD TEST REPORT

RECEIVED

Operator Name Cherwon USA Inc	API Number 30-075-31705
Property Name Vacuum Colerita West Unit	Well No. 65

2. Surface Location

U1 - Lot F	Section 36	Township 17S	Range 34E	Feet from 1572	N/S Line N	Feet From 1492	E/W Line W	County LEA
----------------------	----------------------	------------------------	---------------------	--------------------------	----------------------	--------------------------	----------------------	----------------------

Well Status

T&D WELL YES ☒ NO	SHUT-IN YES ☒ NO	INJECTOR ☒ NO	SWD ☒ NO	OIL ☒ NO	PRODUCER GAS ☒ NO	DATE 5/1/15
---	--	---	--	--	---	-----------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Casing	(E)Tubing
Pressure	0	N/A	N/A	0	850
Flow Characteristics					
Pull	Y/N	Y/N	Y/N	Y/N	CO2 ☒
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR ☒
Surges	Y/N	Y/N	Y/N	Y/N	GAS ☒
Down to nothing	Y/N	Y/N	Y/N	Y/N	Type of Fluid
Gas or Oil	Y/N	Y/N	Y/N	Y/N	Injected for
Water	Y/N	Y/N	Y/N	Y/N	Waterflood if applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

BS 7/14/2015

Signature: Tanner Dellacru	chevron	OIL CONSERVATION DIVISION
Printed name: Tanner Dellacru		Entered into RBDMS
Title: PSA		Re-test
E-mail Address: T22R@chevron.com		
Date: 5/1/15	Phone:	
	Witness: [Signature]	

INSTRUCTIONS ON BACK OF THIS FORM

JUL 15 2015